

## Identification

Taric code: 3822 00 00

# Specifications

concentration.....

1000 mg/l

This standard solution is traceable to Standard Reference Material from NIST.

## Physical data

• Density: 1,01 g/cm<sup>3</sup>

## Safety - GHS

Signal Word:

#### Hazard Statements:

H314: Causes severe skin burns and eye damage.

#### Precautionary Statements:

P260: Do not breathe dust / fume / gas / mist / vapours / spray.

Danger

P303+P361+P353: IF ON SKIN (or hair): Remove / Take off immediately all contaminated clothing. Rinse skin with water / shower.

P305+P351+P338: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P310: Immediately call a POISON CENTER or doctor / physician.

P405: Store locked up.

P501a: Dispose of contents / container in accordance with local / regional / national / international regulations.

## Transport/storage

• ADR: 8 C1 III • UN 3264 • CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.()

- IMDG: 8 III UN 3264 CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. ()
- IATA/ICAO: 8 III UN 3264 CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. ()
- PAX: 852
- CAO: 856
- Store between 15°C and 25°C

